

Product Safety Recall



Kaymar Rear Spare Wheel Carriers

Sold in the period from 1 May 2022 to 30 November 2022

Affected Vehicles		
Landcruiser 75 series	Landcruiser 80 series	Prado 150
Landcruiser 76 series	Landcruiser 100 series	Landcruiser 60 series
Landcruiser 78 series	Hilux 2015 onwards	Ford PX Ranger

Rear Spare Wheel Carrier Product Numbers			
C76L	K8120R	KIT62U-R-JCD	KITHIL-05U-R-JCD
C76R	K8130L	KIT75D	KITHIL-15
C15HL	K8130R	KIT75D-R-JCD	KITHIL-15-L-JCD
K1096	K8140L	KIT76	KITHIL-15-R-JCD
K8020UL	K8140R	KIT76-R-JCD	KITPRADO150-R-JCD
K8020UR	K8220L	KIT76W	KITPRADO150-S-R-JCD
K8040UL	K8220R	KIT76W-R-JCD	KITPRADO151-S
K8040UR	KIT100U-IFS	KIT78D	KITPRADO151-S-R-JCD
K8100L	KIT100U-IFS-L-JCD	KIT78D-R-JCD	KITPRADO152
K8100R	KIT100U-IFS-R-JCD	KIT80U	KITPRADO152-R-JCD
K8105L	KIT100U-LA	KIT80U-L-JCD	KITPRADO153
K8105R	KIT100U-LA-L-JCD	KIT80U-R-JCD	KITPRADO153-R-JCD
K8110L	KIT100U-LA-R-JCD	KITGQU-R-JCD	KITPXRU
K8110R	KIT62U	KITHIL-05U	KITPXRU-L-JCD
K8120L	KIT62U-L-JCD	KITHIL-05U-L-JCD	KITPXRU-R-JCD

Defect: Welds in the product may have insufficient fusion.

Hazard: The product may deform or detach, causing a hazard for road users.

What to do: Consumers should stop using the product to carry a wheel, and contact AutoPacific Australia Pty Ltd trading as Kaymar 4WD Accessories (**Kaymar**) to arrange inspection and replacement.

Contact: Call Kaymar on 1300 583 973 Mon-Fri 9am-5pm.

See productsafety.gov.au for
Australian product recall information